

United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Price Field Office 125 South 600 West Price, Utah 84501

3482 SL-070645 U-47977 (UT-070)

Certified Mail--Return Receipt Requested Certificate No. Z 580 925 459

Mr. Steven E. Kochevar, P. E. Mine Planning Administrator Interwest Mining Company One Utah Center, Suite 2000 Salt Lake City. Utah 84140-0200

Notification of Sealing, 3rd North West Side Panel Block, Deer Creek Mine. # 2 ACT/015018 Mr. Kochevar: Fax PFO, Copy Xx Re:

Dear Mr. Kochevar:

The Bureau of Land Management (BLM) received on August 6, 1999, a request from Interwest to seal mined-out areas in the subject mine. This notification of sealing follows and conforms with 43 CFR 3484.1(c)(7), abandonment of mining areas. The 3rd North West Side longwall block is located on Federal leases U-06039, U-7653, and U-47977.

Interwest proposes to construct permanent seals for the 9th through the 3rd West gateroads each at the tie in to the 3rd North B Mains. Interwest states this would isolate this mined-out longwall gob, reduce ventilation requirements and provide for dewatering of the area.

The BLM agrees with the proposal, as sealing of mined-out areas is a standard practice. Sealing off the west side of the 3rd North longwall gob area reduces the possibility for spontaneous combustion, eliminates worker inspections and exposure, provides controlled dewatering and reduces ventilation requirements.

We also agree that all recoverable coal has been extracted as per the approved resource recovery and protection plan, as modified. We note that all associated mining equipment has been removed and the area has been inspected by our personnel and representatives of the State of Utah Department of Health for verification and any environmental concerns.

The BLM has determined that the proposed sealing and abandonment of the 3rd North west side panel block complies with the Mineral Leasing Act of 1920, as amended, the regulations at 43 CFR 3480, the lease terms and conditions, and maximum economic recovery of the Federal coal has been achieved for this area. Interwest's sealing proposal

is approved as submitted (approved map attached), subject to any requirements of the Mine Health and Safety Administration.

If you have any questions, please contact Stephen Falk of my staff at (801) 636-3600.

Sincerely,

Richard L. Manus

For Richard L. Manus Field Office Manager

Enclosure

Approved Mine Map

cc: UT-921, SD, Utah (w/encl.)

Utah Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210 Salt Lake City, Utah 84114-5801 (w/encl.)

